



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Karl Houskeeper Environmental Scientist	11			

Company Ian McClain Associate Engineer

Inspection Report

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, July 07, 2009
Start Date/Time:	7/7/2009 7:00:00 AM
End Date/Time:	7/7/2009 1:30:00 PM
Last Inspection:	Tuesday, June 09, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 82 Deg. F. InspectionID Report Number: 2055

Accepted by: jhelfric

7/9/2009

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Mineral Ownership

Types of Operations

5,568.00	Total Permitted		
248.50	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Current Acreages

✓ Federal State

County

Other

✓ Underground ☐ Surface

☐ Loadout Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Jaren Jorgensen, Consol, accompanied Ian McClain, Consol, and Karl Houskeeper, DOGM, during the inspection.

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site. This condition is being met.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Tuesday, July 07, 2009

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 07, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 07, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site. This condition is being met.

2. Signs and Markers

The mine ID signs are in place at the points of public access and contain the required information.

4.a Hydrologic Balance: Diversions

The culvert outlet by the new oil and fuel storage building at the 4th East Portal site is nearing 50 % sediment build up. The outlet and drainage leading away from the outlet needs to be cleaned. The grade of the diversion should be checked to assure that the flow and sediment do not collect in front of the culvert outlet.